



*IBM DS8870 Microcode  
Customer Information  
87.0.x.x to Current*

V5.05

# Contents

|   |          |
|---|----------|
| <b>Summary of Changes</b>   | <b>1</b> |
| <b>Document Purpose</b>   | <b>2</b> |
| <b>General Recommendations</b>  | <b>2</b> |
| <b>References</b>   | <b>3</b> |
| <b>DS8870 Information</b>   | <b>3</b> |
| <i>Remote Code Load Support</i>                                       | 3        |
| <i>AOS Considerations</i>   | 3        |
| AOS V4.0  | 3        |
| AOS V3.3  | 3        |
| <i>VPN</i>  | 4        |
| <i>Modem Support</i>  | 4        |
| <i>IBM Call Home</i>  | 4        |
| <i>Broadcom (formerly Brocade) Switches and Concurrent Code Loads</i> | 4        |
| <i>Storage Manager GUI</i>  | 5        |
| <b>Copy Services</b>  | <b>5</b> |
| <i>PPRC Possible Loss of Access</i>                                   | 5        |
| <i>Global Mirror and Fast Reverse Restore</i>                         | 5        |
| <b>IBM System Z</b>   | <b>6</b> |
| <i>System Storage Fabric Backbones</i>                                | 6        |
| SAN768B-2 Fabric Backbone   | 6        |
| <i>z/OS Systems</i>   | 6        |
| Incremental FlashCopy with 'Preserve Mirror=Required'                 | 6        |
| Sysplex / CFRM Couple Data Sets (CDS) and PPRC                        | 6        |
| z/OS Global Mirror (formerly eXtended Remote Copy [XRC])              | 7        |
| Messages that may be seen during a microcode upgrade                  | 7        |
| Concurrent Copy sessions  | 7        |
| FICON Direct-attached devices and 8Gb Host Adapters                   | 7        |
| z/OS Hosts running PPRC   | 8        |
| zHPF Environments   | 8        |
| <i>z/VM Systems</i>   | 8        |
| z/VM Red Alert Web Page   | 8        |
| <i>z/VSE Systems</i>  | 8        |
| (E)CKD disks  | 8        |
| FCP-attached SCSI disks   | 8        |

## Summary of Changes

| Date             | Change  |
|------------------|---|
| 14 February 2020 | Correct Call Home IP address for eccgw01.boulder.ibm.com  |
|                  | Add recommendation that no DS8000 configuration changes are to be made after acquisition.   |
| 07 January 2021  | Added minimum microcode level to support Remote Code Loads.<br>Include notice of VPN support no longer available.<br>Updated IBM Call Home Host names and IP addresses. |
| 06 October 2021  | Update AOS V4.0 DNS names.  |
| 25 October 2021  | Updated the link for Flashes, Alerts and Bulletins  |
| 26 May 2022      | Updated the 'General Recommendations' section.  |

## Document Purpose

The information contained in this document is to inform you of:

- Actions that may need to be taken prior to a microcode upgrade.
- Recommendations regarding Operating Systems, APARs, and Copy Services.
- Messages that may be posted during the microcode upgrade.

## General Recommendations

### !!! IMPORTANT !!!

Once a microcode bundle has been downloaded, **no changes** are to be made to the DS8000 configuration as it may adversely affect the upgrade process. If changes are made, unpredictable results may occur, such as repeated warmstarts or loss of access to attached Host systems.

During a microcode activation, regardless of it being performed by Client, SSR, or via Remote Code Load (RCL), the following should be avoided:

- IPL of Host Operating Systems.
- Changes to Copy Services configurations.

If you wish to make configuration changes after microcode has been downloaded, please contact IBM Support and request to have the preload canceled and rescheduled.

### Note

During a microcode upgrade, access to DSCLI and the DSGUI will not be available. CSM installed elsewhere will be disconnected from the DS8870 that is being upgraded.

All Copy Services functions: Metro Mirror, Global Mirror, etc., will continue to be active during this time.

## References

### Note

On 15 October 2019, IBM announced Withdrawal of Services for the DS8870 Model 961, effective 31 December 2020. For more details, please go to

<https://www-01.ibm.com/common/ssi/cgi-bin/ssialias?infotype=AN&subtype=CA&htmlfid=897/ENUS919-176&appname=USN>

IBM DS8000 Code Recommendations:

<https://www.ibm.com/support/pages/ds8000-code-recommendation>

DS8870 Code Bundle Information (includes Release Notes):

<https://www.ibm.com/support/pages/ds8870-code-bundle-information>

DS8870 Flashes, Alerts and Bulletins:

<https://www.ibm.com/support/pages/ibmsearch?tc=ST8NCA&dc=DD200+D600+DB600+DC6A40&sortBy=desc>

My Notifications – keep up to date by subscribing for updates about installed Hardware and Software: <https://www.ibm.com/support/mynotifications>

IBM System Storage Interoperation Center's (SSIC) interoperability matrix:

<https://www-03.ibm.com/systems/support/storage/ssic/interoperability.wss>

## DS8870 Information

### Remote Code Load Support

To take advantage of Remote Code Loads, the microcode level must be at 87.51.95.0.

### AOS Considerations

#### AOS V4.0

Customers must open network **Port 443** and add the following addresses to their firewall settings to allow for outbound-initiated support connections.

- <https://aoshats.us.ihost.com>
- <https://aosrelay1.us.ihost.com>

This is applicable for microcode levels 87.50.114.0 and higher.

#### AOS V3.3

Customers using embedded AOS on microcode levels at or below 87.41.44.0 must update their firewall setting as stated above for AOS V4.0, before upgrading to R7.5 bundle levels.

# IBM DS8870 Microcode Customer Information

## 87.0.x.x to Current

---

### VPN

Customers that use VPN for call home and/or remote support must configure call home over SSL, and either AOS V4.0 or RSC for remote support.

#### Note

Effective 01 January 2021, VPN support is no longer available.

### Modem Support

Modem support has been discontinued as of 30 June 2017. Broadband connections are now recommended. For more information about this, please go to <https://www.ibm.com/support/pages/ds8000-call-home-and-remote-support-modem-need-move-broadband-connections>.

### IBM Call Home

This function may encounter failures if the following IP addresses and ports are not configured and enabled in your firewall settings. Please ensure that the following are added.

For DS8870s that are below 87.52.x.x –

| Host                      | IP Address    | Port | Protocol |
|---------------------------|---------------|------|----------|
| eccgw01.boulder.ibm.com   | 207.25.25.197 | 443  | https    |
| eccgw02.rochester.ibm.com | 129.42.160.51 | 443  | https    |
| www.ecurep.ibm.com        | 192.109.81.20 | 443  | https    |

For DS8870s that are at 87.52.x.x and above –

| Host             | IP Address    | Port | Protocol |
|------------------|---------------|------|----------|
| esupport.ibm.com | 129.42.54.189 | 443  | https    |
| esupport.ibm.com | 129.42.56.189 | 443  | https    |
| esupport.ibm.com | 129.42.60.189 | 443  | https    |

For more information, please go to:

<https://www-03.ibm.com/support/techdocs/atsmastr.nsf/WebIndex/PRS4743>.

### Broadcom (formerly Brocade) Switches and Concurrent Code Loads

Customers using Broadcom switches FOS 7.0 levels up through 7.1.1 or 7.2.0 are exposed to an issue where the switch may reboot continuously. For more information regarding this exposure, please reference

<http://www-01.ibm.com/support/docview.wss?uid=ssg1S1004578>.

### Storage Manager GUI

Starting with microcode level 87.10.102.0<sup>i</sup>, HTTP access has been disabled. This includes SSPC or browser. Please access the Storage Manager GUI using **https** and **port 8452**.

Example: **https://<IP address of HMC>:8452/DS8000**.

## Copy Services

### PPRC Possible Loss of Access

If the Primary and Secondary DS8870s are not running 87.10.91.x<sup>i</sup> or higher, a potential Loss of Access condition may occur during a microcode upgrade. To avoid this potential issue, the following options are recommended.

1. Update the microcode on the Primary DS8870 first. This will avoid the issue.
2. Suspend the PPRC session(s), then the DS8870s may be upgraded in either order. This may be desirable when the PPRC Primary is also a PPRC Secondary as it will prevent the possibility of a Loss of Access.

### Global Mirror and Fast Reverse Restore

For those Customers who are at 87.40.140.0<sup>i</sup> and below, a condition exists where a Fast Reverse Restore (FRR) on Global Mirror (GM) secondary volume(s) may result in fenced volumes causing the GM to go into a FATAL status. This is corrected in 87.40.141.0<sup>i</sup> and higher. Mitigation steps are available to prevent this.

- Before performing an FRR, remove all GM FlashCopy relationships and then re-establish them.
- This is required once, even after the microcode has been upgraded to a level that contains the correction.

### Note

If an Active / Standby CSM server configuration is in place, they must be at the [same CSM release](#) in order to communicate with each other. During the time they are at disparate releases, attempts to connect them will result in CSM error message **IWNR3016E** or **IWNR3051E Reason Code 114**.

## IBM System Z

### System Storage Fabric Backbones

#### [SAN768B-2 Fabric Backbone](#)

Fabric OS (FOS) Version 7.3.0b includes defects that can cause fabric interruption or outage in FICON or FCP environment. A high number of Request Diagnostic Parameter (RDP) requests from DS8870 model 961 using 16 Gb links can overdrive the director's CP card to the point where it can cause the backup CP to fault the primary.

FOS V7.3.0b5 has been qualified for use in FICON|FCP environments, per the qualification letter posted on the [IBM z Systems FICON|FCP](#) web page (FOS V7.4.0a is recommended).

### z/OS Systems

#### Note

The entries following are not exhaustive. It is strongly recommended that PSP Buckets or FIXCATs be reviewed prior to any microcode upgrade, in addition to reviewing the Footnotes section of the DS8000 Code Recommendation web page. Alerts, Flashes, and Bulletins should also be reviewed as listed in the [References](#) section at the beginning of this document.

#### [Incremental FlashCopy with 'Preserve Mirror=Required'](#)

Environments using this function may encounter a problem if used while the Primary DS8870 is at R7.4<sup>1</sup> and higher, while the Secondary DS8870 is at R7.3 and lower. The problem can occur during a DS8870 microcode upgrade if the PPRC Primary is updated first, or if a failover/HyperSwap is performed after updated the Secondary. If this scenario is possible, please contact IBM Support in advance for a workaround (ID 319535).

#### [Sysplex / CFRM Couple Data Sets \(CDS\) and PPRC](#)

A condition exist that causes a primary volume in a PPRC pair to stay in a long busy state (does not respond to the Host system) after a warmstart on the secondary volume in the PPRC pair. The primary volume will stay in the long busy state until I/O is re-driven to the volume, or a state change interrupt occurs on the volume. A time-out of the Sysplex primary CDS will cause the Sysplex to switch to the Alternate CDS. If the Alternate CDS volume times out, this will cause a Sysplex-wide failure. Sysplex customers should not include volumes containing any Sysplex CDS in an active PPRC pair, except for the LOGR CDS.

For example: a concurrent microcode code load could possibly see a warmstart and cause this problem to occur. Customers who do not exclude Sysplex / Coupling Facility Resource



## IBM DS8870 Microcode Customer Information 87.0.x.x to Current

---

Management (CFRM) CDSs from an active PPRC relationship MUST remove or suspend those PPRC pairs of volumes with Sysplex/CFRM CDSs prior to a microcode upgrade.

### [z/OS Global Mirror \(formerly eXtended Remote Copy \[XRC\]\)](#)

System Data Mover (SDM) APARs **OA54082**, **OA55040**, and **OA55162** are required to be APPLY'd prior to DS8870 microcode upgrades. This applies to 87.51.52.0<sup>i</sup> and higher.

Clients employing Erase on Scratch (EOS) in an z/OS GM (zGM) environment should review APAR **OA55742** as excessive delays on the secondary may be seen via message ANTX8117I during EOS activity.

### [Messages that may be seen during a microcode upgrade](#)

Message IEA074I may also be seen during a microcode upgrade and considered normal. For example:

**IEA074I MODERATE CONTROLLER HEALTH,MC=cc,TOKEN=dddd,SSID=xxxx,  
DEVICE NED=tttt.mmm.ggg.pp.ssssssssssss.uuuu,RANK|DA|INTF=iiii,text**

Specifically, Message Codes (MC):

| MC | Description  |
|----|--|
| 09 | SFI CODE ACTIVATION IN PROGRESS                    |
| 0A | SFI CODE ACTIVATION COMPLETE                       |
| 0B | HOST ADAPTER CODE ACTIVATION IN PROGRESS           |
| 0C | HOST ADAPTER CODE ACTIVATION COMPLETE              |
| 22 | PPRC SECONDARY CONTROLLER FAILOVER RECOVERY ACTION |
| 23 | PPRC SECONDARY CONTROL FAILBACK RECOVERY ACTION    |

Note: this is a subset of the Message Codes related to this message. For more information, please review message IEA074I at

<https://www.ibm.com/docs/en/zos/2.5.0?topic=messages-iea074i>

### [Concurrent Copy sessions](#)

This type of session will be terminated during a microcode upgrade. You may want to terminate these sessions prior to the upgrade.

### [FICON Direct-attached devices and 8Gb Host Adapters](#)

During a microcode upgrade, the Host Adapter (HA) firmware is updated. If 8Gb HAs are installed and FICON direct attached, the following message may be seen:

**IOS050I CHANNEL DETECTED ERROR ON 3BD4,3E,\*\*,\*\*02,PCHID=0285**

## IBM DS8870 Microcode Customer Information 87.0.x.x to Current

---

These are normal during the HA update phase and will recover automatically. You may see a number of these messages. In addition, you may also see message IEA498I as discussed below, or IEA074I listed above.

### [z/OS Hosts running PPRC](#)

During the Host Adapter (HA) updates of a microcode upgrade on a PPRC primary or secondary storage subsystem, the partner subsystem may post the follow message:

**IEA498I B000, ONLH4Z, PPRC-PATH ONE OR MORE PPRC PATHS REMOVED  
UNEXPECTEDLY SSID=B000 (PRI)=0175-FRBK1, CCA=00**

These messages are considered normal; the PPRC paths will be automatically recovered.

### [zHPF Environments](#)

Customers planning to use zHPF must install APAR **A39087** (Media Manager), **OA38939**, **OA39130**, plus PRE-REQs **OA38966** and **OA38925** prior to upgrading to microcode level 87.0.184.0 and higher. *It is strongly recommended that zHPF is disabled until all software and microcode levels are updated.*

### [z/VM Systems](#)

#### [z/VM Red Alert Web Page](#)

Prior to a DS8870 microcode upgrade, this web page must be checked as it provides information about high-impact items that are associated with z/VM. Please review <http://www.vm.ibm.com/service/redalert/> prior to a microcode upgrade, as preventative service may need to be put on prior to the upgrade.

### [z/VSE Systems](#)

#### [\(E\)CKD disks](#)

z/VSE strongly recommends that all z/VSE systems be shut down for local disks and if remote disks are coupled via PPRC, prior to a DS8870 microcode upgrade.

#### [FCP-attached SCSI disks](#)

z/VSE does not support concurrent microcode upgrades for FCP-attached SCSI disks. Please ensure that the following steps are performed:

1. Shutdown the z/VSE system(s)
2. Allow IBM to perform the microcode upgrade
3. IPL the z/VSE system(s)

This recommendation includes all dependent z/VSE systems, e.g., those z/VSE systems that use the same lock file.

---

<sup>i</sup> This is below the minimum recommended microcode level. Consider upgrading to the 'Recommended "go to" Level' (87.52.45.0 [R7.5 SP13.1]).