Release Date: May 8, 2012

VRMF Level Data Results:

VRMF level From:	86.20.114.0
VRMF Level To:	86.20.117.0
Report for:	All DS8800

Code Bundle Contents

Level	SEA or LMC Version: Used with dscli <i>ver</i> command.	CLI Client Level	Storage Manager Code Level
86.20.117.0	7.6.20.570	7.6.20.570	5.6.20.1127

Overview of new features and functions supported by Microcode Release 86.20.101.0 for DS8800, 242x model 951.

At a glance:

none

This is a new microcode release only supports the DS8800.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact. Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

1 HIPER - Acute: An irrecoverable error with potential loss of data.

- Serious: An irrecoverable error with potential loss of access to data.

2 Moderate - A function not operational and/or performance might be degraded.

3 Service - A recoverable error (no impact) and service improvements.

4 Improvements - Improvement changes for better Usability and Serviceability.

Pervasive: Problems with 3 or more occurrences

Acute: An irrecoverable error with potential loss of data.

Internal I/O fabric error results in a cache and NVS mis-compare

1. Problem Description: An internal I/O fabric error can result in data loss when a mis-compare for cache and NVS data is detected. This will result in multiple sector data loss.

2. Potential Impact of Problem: loss of data

3. Problem Severity: HIPER 4. Pervasive Problem: Yes

ID#: 267503

Serious: An irrecoverable error with potential loss of access to data.

Unit abort when zOS writing to a FlashCopy target with link errors

1. Problem Description: http://www.ibm.com/support/docview.wss?uid=ssg1S1004077

2. Potential Impact of Problem: loss of access

3. Problem Severity: High Impact

4. Pervasive Problem: No

ID#: 270451

Moderate: A system path is not operational and performance might be degraded.

None

Service: A recoverable error, Service improvements.

None

Improvements: Improvement for better usability

None

Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries
- > S/390
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at http://www.ibm.com/legal/us/en/copytrade.shtml. Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

Notices

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing IBM Corporation North Castle Drive Armonk, NY 10504-1785 U.S.A.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law: INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.