Release Date: February 26, 2019

VRMF Level Data Results:

| VRMF level From: | 88.51.49.0 |
|------------------|------------|
| VRMF Level To: | 88.51.53.0 |
| Report for: | All DS8880 |

Code Bundle Contents

| DS8880 Code Bundle Level | SEA or LMC Version: | DSCLI Client | Heat Map Transfer Utility | Storage Manager | Copy Services Manager |
|-----------------------------|------------------------|--------------|------------------------------|-----------------|--------------------------|
| 88.51.53.0 | 7.8.51.159 | 7.8.51.159 | 7.8.51.159 | 5.8.51.1060 | 6.2.4 |

Overview of new features and functions supported by this release

At a glance:

- Capacity intermix in HPFE Gen2 Enclosures
- Code fixes

This new microcode release supports DS8880 systems only.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact. Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

| 1 | High Impact | Acute: An irrecoverable error with potential loss of data.Serious: An irrecoverable error with potential loss of access to data. | | | |
|---|--------------|---|--|--|--|
| 2 | Moderate | - A function not operational and/or performance might be degraded. | | | |
| 3 | Service | - A recoverable error (no impact) and service improvements. | | | |
| 4 | Improvements | - Improvement changes for better Usability and Serviceability. | | | |

HIPER: High Impact problem that is Pervasive: 3 or more occurrences

Acute: An irrecoverable error with potential loss of data.

None.

Serious: An irrecoverable error with potential loss of access to data.

HIPER Multiple 0x0109 MLEs and LPAR failover

- 1. **Problem Description:** Adding Flash storage capacity or replacing Flash Drives, may cause multiple Microcode Logic Errors and LPAR failover in systems running 88.51.49.0 code bundle.
- 2. Potential Impact of Problem: Temporary loss of access
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID# 340309, 341973

0x014E MLE and LPAR reboot during CDA to R8.5

- 1. **Problem Description:** A hardware problem during Code Distribution and Activation from R8.4 or earlier levels, to R8.5, may result in a loss of access.
- 2. Potential Impact of Problem: loss of access
- 3. Problem Severity: High Impact
- 4. Pervasive Problem: No

ID# 340535

Moderate: A system path is not operational and/or performance may be degraded.

Very slow response from DSCLI 'lsckdvol' or 'lsfbvol' command

- 1. **Problem Description:** lsckdvol or lsfbvol command response very slow in systems running R8.5 levels of code, with a large number of volumes.
- 2. Potential Impact of Problem: DSCLI command timeouts
- 3. Problem Severity: Moderate
- 4. Pervasive Problem: Yes

ID# 339984

HMC2 WebUI fails to start after update to R8.5

- **1. Problem Description:** A file left over from manufacturing caused the HMC hostname to revert to 'localhost2'.
- 2. Potential Impact of Problem: Loss of access to HMC2
- 3. Problem Severity: Moderate
- 4. Pervasive Problem: Yes

ID# 340441

Service: A recoverable error, Service improvements.

None.

Improvements: Improvements for better usability

None.

Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries
- > S/390
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at http://www.ibm.com/legal/us/en/copytrade.shtml. Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

Notices

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing

IBM Corporation

North Castle Drive

Armonk, NY 10504-1785

U.S.A.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law: INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.