Release Date: 24 May, 2024

VRMF Level Data Results:

VRMF level From:	88.59.51.0
VRMF Level To:	88.59.53.0
Report for:	All DS8880

Code Bundle Contents

DS8880 Code Bundle Level	SEA or LMC Version:	DSCLI Client		Storage Manager	Copy Services Manager
88.59.53.0	7.8.59.249	7.8.59.249	7.8.59.249	5.8.59.1092	6.3.7

Overview of new features and functions supported by this release

At a glance:

- PPRC path compatibility for DS8A00
- Code fixes

This new microcode release supports DS8880 systems only.

Select Modifications Included in this Release Note:

This is a list of some modifications contained across one or more LIC (License Internal Code) or microcode release(s). The potential impact is variable. Specific environments may aggravate or degrade the potential impact. Problem(s) fixed and reported in this release note may not be in higher levels of code bundles.

Definition of Problem Severity:

1	High Impact	Acute: Irrecoverable error with potential loss of data.Serious: Irrecoverable error with potential loss of access to data, or critical function.	
2	Moderate	- A function not operational and/or performance might be degraded.	
3	Service	- A recoverable error (no impact) and service improvements.	
4	Improvements	nents - Improvement changes for better Usability and Serviceability.	

HIPER: High Impact problem that is Pervasive: 3 or more occurrences

Acute: An irrecoverable error with potential loss of data.

None.

Serious: An irrecoverable error with potential loss of access to data, or critical function.

None.

Moderate: A system path is not operational and/or performance may be degraded.

None.

Service: A recoverable error, Service improvements.

SNMP trap configuration missing after HMC rebuild

- 1. Problem Description: HMC backup didn't include SNMP trap config for base feature
- 2. Potential Impact of Problem: SNMP failure
- Environment: All R8 and R9
 Problem Severity: Service
 Pervasive Problem: No

ID# 365210

Improvements: Improvements for better usability

Mapping for PPRC connections to DS8A00 Host Adapters

- **1. Problem Description:** Provide capability to create PPRC paths to DS8A00 Host Adapters in physical slots 3 and 6
- 2. Potential Impact of Problem: PPRC path compatibility
- **3. Environment:** DS8880 and DS8900F connecting to DS8A00
- 4. Problem Severity: Improvement
- 5. Pervasive Problem: No

ID# 363545

New IBMAPKI Certificate

- 1. Problem Description: Add new IBMAPKI certificate for Assist OnSite (AOS)
- 2. Potential Impact of Problem: None
- 3. Environment: All
- 4. Problem Severity: Improvement
- 5. Pervasive Problem: No

ID# 363741

Trademarks

The following terms are trademarks of the International Business Machines Corporation in the United States, other countries, or both.

- > AIX
- > Enterprise Storage Server
- > ESCON
- > FICON
- > i5/OS
- > iSeries
- > IBM
- > pSeries
- > S/390
- > System Storage
- > TotalStorage
- > z/OS
- > zSeries

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the web at Copyright and trademark information at http://www.ibm.com/legal/us/en/copytrade.shtml. Adobe, the Adobe logo, PostScript, and the PostScript logo are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States, and/or other countries.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

Linux is a trademark of Linus Torvalds in the United States, other countries, or both.

Microsoft, Windows, and Windows NT are trademarks of Microsoft Corporation in the United States, other countries, or both.

© Copyright IBM Corp. 2004, 2011

Notices

This information was developed for products and services offered in the U.S.A. IBM may not offer the products, services, or features discussed in this document in other countries. Consult your local IBM representative for information on the products and services currently available in your area. Any reference to an IBM product, program, or service is not intended to state or imply that only that IBM product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any IBM intellectual property right may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any non-IBM product, program, or service.

IBM may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing

IBM Corporation
North Castle Drive
Armonk, NY 10504-1785
U.S.A.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law: INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATIONS "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.